Work Order ID 56984

Quality Control

Tuesday, March 16, 2010 10:28:42 AM



Page 1

(2)

10.03.19

D4035-041 Item ID: Accept Setup Start Revision ID: Stop Lid Rib Assembly, Fwd (350 Basket) Item Name: Start Qty: 7.00 3/16/2010 Start Date: Cust Item ID: Req'd Qty: 4.00 Required Date: 3/23/2010 Customer: Reference: Run Start Process Plan: MF Date: 10-3-16 Tooling: Approvals: Date: Stop SPC (Y/N): QC: Date: Date: Sequence ID/ Operation Set Up/ Draw Plan Reject Reject Draw Accept Insp. Description Number Stamp Work Center ID **Run Hours** Number Rev. Code Qty Qty Draw Nbr Revision Nbr D4035 A Weld per dwg A/R S.S. rod Batch: 1/1/092/2 100 0.00 0.00 Large Fab Memo Large Fab 1- Cut D4035-1 as per dwg D4035 2- Drill as per dwg D4035 using DT9562 3- remove identification marks and deburr 4- Weld bushing in rib as per dwg D4035 QC9- Inspect visual per QSI004- Fusion Welds 110 0.00

0.00

Memo

W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAP	NGE	Ву	Date	Approval QC Inspector		
				Ţ					
Part No		PAR #:		jory:					
NCR:		(A)		R NON-CONFORMAL				_ Date: _	
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
									4

Work Order ID 56984

Tuesday, March 16, 2010 10:28:42 AM



Page 2

Item ID:

D4035-041

Accept

Setup Start



Revision ID:

Item Name: Lid Rib Assembly, Fwd (350 Basket)

Start Date:

3/16/2010

Start Qty: 1.00

Required Date: 3/23/2010

Req'd Qty: 1.00



Cust Item ID:

Customer:

Draw

Number

Run Start

Stop

Reference: Approvals:

Process Plan:

Date:

Tooling:

Date:

Stop

OC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Plan

Code

Accept Reject

Qty

Reject

Insp. Number Stamp

Sequence ID/ Work Center ID

120

QC

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

0.00

Swlosha Swloslas

0.00

Qty

Packaging

Identify as per dwg & Stock Location: WA 10

Memo

Memo

0.00 0.00

Packaging

140

QC21- Final Inspection - Work Order Release

0.00

Quality Control

Memo

0.00

10/03/2499 MF 10-3-23

									DE SENSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRES
W/O:			WC	RK ORDER CHANG	ES		,		
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									1000
							- 1		
Part No		PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQ	A:	Date:	
Resolution:			Disposition	1;	QA: N/C CIG	sed:		_ Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR)	4.		
DATE	STEP	Description of NC	Corrective Action Section B			Verific	ation	Approval	Approval
DAIL	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
									110-1
			-					Tell	
			=						
								17.00	
								120-000	1.01
	9 3								
	1 1 1 1 1 1							100 100 100	The state of the s

Picklist Print

Tuesday, March 16, 2010 10:28:42 AM

Work Order ID: 56984

Parent Item: D4035-041

Lid Rib Assembly, Fwd (350 Basket)

Parent Item Name: Comments:

IPP RevA: new issue DD 09.11.25 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 3/16/2010

Start Qty: 1.00

Required Date: 3/23/2010

Required Qty: 1.00

Component Item ID/ Item Name D2327-3

Replacement Mfg/ Item ID

Purch Manufactured Bin Primary Item Location No

No

Last Location Route Seq ID 100

Unit of Qty on Measure Hand Each

Remaining Qty To Pick 37.0000 1.0000

Qty Issued Date Issued

Status

Page 1

Spacer Bushing

Warehouse Loc Oty Loc Code Location

Main Warehouse

ST

44274 44365 Main Warehouse

> 55167 55917

20 100 f

13

170.5455 1.8421

M304TS0.750W.049

Purchased


304 SQ Tube .75x.75x.049W

Warehouse Loc Qty Loc Code Location


Main Warehouse

MAT 170.5455158 106604 2.4123 107460 28.2726 113763 139.860616


W/O:			WO	RK ORDER CHANG	ES	Total	A THE		123
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							e e		
Part No	Part No:	PAR #:	Fault Cate	gory:	_ NCR: Yes 1	No DQ	A:	_ Date: _	
	R	lesolution:	Disposition	n:	_ QA: N/C Clo	sed:	- L	Date: _	
NCR:			WORK ORDE	ER NON-CONFORM	ANCE (NCR))			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sect Action Description Chief Eng	on B Sign & Date		cation ion C	Approval Chief Eng	Approval QC Inspector
						Date			
2									
						= 1			



W/O:			V	VORK ORDER CHANG	ES	1.0			Car.		
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	Part No:	PAR #:		tegory:					Approval QC Inspector		
NCR:	A CONTRACTOR		- Little	ion: DER NON-CONFORM				Date: _			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	Sign	& Spri	cation ion C	Approval Chief Eng			
			Chief Eng	Chief Eng	Date						




W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
							(P)		
		PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:		_ Date: _	
	Re	esolution:	Disposition	;	QA: N/C Cld	sed:		_ Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			, 111
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign &	Verifica Section		Approval Chief Eng	Approval QC Inspector
								1	




Dart Aerospace L	.td
------------------	-----

W/O:			WO	RK ORDER CHANG	GES							
DATE	STEP	PRO	OCEDURE CHAP	NGE		Ву	Date	Date Qty Approval Chief Eng / Prod Mgr QC In:				
								**	Date: Date:			
Part No	Part No:	PAR #:		jory:								
Resolution:				A The same of the					_ Date: _	"Printella"		
NCR:	Y V		WORK ORDE	R NON-CONFORM	ANCE (NCR)					
DATE	1 15	Description of NC			ction B		Verific	cation	Approval	Approval		
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		on C	Chief Eng	QC Inspector		
									+			
*												



W/O:			WO	RK ORDER CHANG	ES	3.1		The Salar				
DATE	STEP	PRO	OCEDURE CHAP	NGE	Ву	Date	Date Qty Approval Chief Eng / Prod Mgr					
	PAR #:	Fault Categ	gory:	NCR: Yes	No DQ	A:	_ Date: _					
	R	esolution:	Disposition	1;	_ QA: N/C C	losed:		Date:				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)						
DATE	STEP	Description of NC	Initial	Corrective Action Sect Action Description	ion B Sign		ation		Approval			
	77	Section A	Chief Eng	Chief Eng	Date	Secti	on C	Chief Eng	Approval QC Inspector			
	i ai							21.				
4-11												
								7.7				
		1.0										
									L. Ledi			



W/O:			W	ORK ORDER CHANG	GES				133				
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									ž				
Part No	1000	PAR #:		egory:									
	R	esolution:		on:					_ Date: _				
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)						
DATE	STEP	Description of NC			tion B		Verific	ation	Approval	Approval			
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti			QC Inspector			
•													
					•								